Standard Operating Procedure SOP No. PVDF Coupons 7.026

DCR No.: 97006 Revision No.: New Effective: 6-11-97 Supersedes: New Revision Date: New Page No.: 1 of 2

1 Purpose

1.1 To establish how often polyvinylidene fluoride (PVDF) coupons are generated and when submission to the quality control inspector (QCI) for approval is necessary.

2 Scope

2.1 This procedure applies to PVDF piping systems.

3 Responsibility

- 3.1 Quality control inspector (QCI) shall manager the bonders or bonding operators and verifies compliance with this procedure.
- Qualified bonder or bonding operator, certified under SOPs 5.028 through5.032 (Bonding Procedures) is responsible for performing and documenting the following procedures.

4 Procedures

- 4.1 PVDF coupons are made when the following conditions occur:
 - 4.1.1 As per customer's requirement.
 - 4.1.2 When bonder to be qualified, performs a specific PVDF bonding procedure, which is described in the SOPs 5.028 through 5.032.
- 4.2 Label each PVDF coupon and document in the Form FN 7.026.1 (PVDF Coupon Log).
- 4.3 Submit coupons to QCI.

5 Review and Approval

5.1 No approval is necessary.

Revision No.	SOP No.	Page
New	7.026	2 of 2

Document Approval

Kon	Laura	
Field Operations Manager		

5-27-97

Date

Cuality Control Manager

Quality Assurance Manager

Date